

**INVENTORY FOR ONE TIME REPAIR OF COMPUTER & ACCESSORIES IN DUSIB**

S.NO	SECTION	ADD	ROOM NO.	CPU SERIAL NO.	PROCESSOR / MOTHER BOARD	PRINTER	UPS	Possible Faulty Parts & Unit	Repair/Replacement Cost Item-Wise (in Rs)	TOTAL
				<b>HEAD QUARTER</b>	<b>PUNARWAS</b>	<b>BHAWAN,</b>	<b>I.P.</b>	<b>ESTATE,</b>	<b>N. DELHI-2</b>	
1	PARLIAMENT CELL	P. B.	38	2F-ADA48	Intel P-III (866MHZ) 20 GB HDD 128 MB RAM	HP-Laser jet 1007	ELNOVA	UPS Mouse		
2	FO TO CE(S) EE (E204)	P. B.	31 A-1	2F-ACY53	Intel P-III 20GB HDD 128 MB RAM	HP-6L Faulty		UPS Keyboard Mouse		
3	CD-I	---	100	2F-ACY29	INTEL P-II (64 MB) RAM 20GB HDD	HP-1007 LJ 6L PRO	AARKAY	Mouse Keyboard		
4	A.C-A(C) -I		202/3	AWPO90TO7383819	P-4(ACER) (256MB)	HP LJ 1020		UPS Keyboard Mouse		
5	EELAE-I EE (EMF-I)			2F-TG035	IBM (P-4) 1500MHZ 128MB RAM	HP LJ 1000	ELNOVA	UPS Keyboard Mouse		
6	OFFICE OF (PA) CEO	P. B.	35			HP-6L		Printer UPS		
7	SURVEY OFFICE (L&L)		K-2		Intel P-III (1.6GHZ) 20 GB HDD 256MB RAM	HP LJ 6L PRO		Printer Mouse Keyboard, Computer		
8	P & M (DIVISION)	V.K	G - 9	AWP090TO7263636 724SE	ACER P-IV 3.0 GHZ HDD-80 GB RAM - 256 MB	HP- 1020	CSS	Mouse		
9	AD(DEMOLITION)	V. K.	B-8	IBM P4 2F-AT624(1)		HP-6L GOLD		Computer HDD(80GB) Printer Keyboard Mouse		

**INVENTORY FOR ONE TIME REPAIR OF COMPUTER & ACCESSORIES IN DUSIB**

S.NO	SECTION	ADD	ROOM NO.	CPU SERIAL NO.	PROCESSOR / MOTHER BOARD	PRINTER	UPS	Possible Faulty Parts & Unit	Repair/Replacement Cost Item-Wise (in Rs)	TOTAL
10	ALLOTMENT BRANCH	V. K.	C-11	IBM P4 2F-NF57				Motherboard HDD(80GB) Keyboard Mouse		
11	PLAN AO (HQ)JJ	V. K.	B-4/A	2F-KT233	Intel P-III (1000MHZ) 20GB HDD 128 MB RAM	HP- 1000	ELNOVA	Keyboard		
12	SURVEY OFFICE(SAC)	V. K.	K-6		Intel P-III (1000MHZ) 20 GB HDD 64+256 MB RAM	DJ-3325		Monitor Keyboard, Printer, UPS.		
13	ESSTT.BRANCH	V.K	F-4			HP6L GOLD HP6L PRO		Printer		
14	A.D.(System)	P.B.	43	AWP23GT13291564 01ZE	acer power series	HP LJ (1020)		Printer		
15	DY. DIRECTOR (Rehab.)	V.K.	C3	INI73203MZ	HP DUAL CORE 3.0 GHz 512 MB RAM 160 GB HDD	1 No. 1020 HP LJ	1 No. (APC 650 VA)	UPS		
16	AD CARE TAKER	V.K	f-8	INI73203ZR	HP DUAL CORE 3.0 GHz 512 MB RAM 160 GB HDD		1 No. (APC 650 VA)	UPS		
17	CRGMS Admn. Section	VK	F-4	INI73203TN	HP DUAL CORE 3.0 GHz 512 MB RAM 160 GB HDD	1 No. 1020 HP LJ Printer 1 1007	1 No. (APC 650 VA)	UPS		
18	AO(HQ)	V.K	E-1	SGS7450SYL	HP DUAL CORE 1.6 GHz 1 GB RAM 250 GB HDD	HP LJ P1005	UNILINE	Keyboard		

**INVENTORY FOR ONE TIME REPAIR OF COMPUTER & ACCESSORIES IN DUSIB**

S.NO	SECTION	ADD	ROOM NO.	CPU SERIAL NO.	PROCESSOR / MOTHER BOARD	PRINTER	UPS	Possible Faulty Parts & Unit	Repair/Replacement Cost Item-Wise (in Rs)	TOTAL
19	UID	V.K	B-9	AWP18GT201846 6099ZE	ACER power series	HP LASERJET 1007	SUPRA	UPS		
20	AD(System)/BMO	P.B.	43			HP LJ 1020		Printer		
21	CONSULTANT ASSETS	VK	H-15	HP- MACHINE				Monitor		
22	HAU SECTION	V.K.	E-11					UPS		
23	COMPUTER SECTION	PB	15	ACER CPU OF BVK				Computer RAM		
24	ESSTT.	V.K	F-4	Acer (AWP23GT13291563 93ZE)				Computer UPS		
<b>ACER COMPURERS IN HQ</b>										
25	E&M	V.K	A-2		ACER P-IV 3.0 GHZ HDD-80 GB RAM - 256 MB			Monitor		
26	PLANNING	V.K	H-2		ACER P-IV 3.0 GHZ HDD-80 GB RAM - 256 MB			Monitor Keyboard Mouse		
27	DD(Reh)	V.K	E-18	AWP090TO7463636 73SE	ACER P-IV 3.0 GHZ HDD-80 GB RAM - 256 MB		UNILINE	Mouse UPS		
28	FA	P.B.	31	AWPO90TO74636 3652 SE	ACER P-IV 3.0 GHZ HDD-80 GB RAM - 256 MB	HPLJ 1020	UNILINE CCS	Computer UPS		

**INVENTORY FOR ONE TIME REPAIR OF COMPUTER & ACCESSORIES IN DUSIB**

S.NO	SECTION	ADD	ROOM NO.	CPU SERIAL NO.	PROCESSOR / MOTHER BOARD	PRINTER	UPS	Possible Faulty Parts & Unit	Repair/Replacement Cost Item-Wise (in Rs)	TOTAL
29	LAW SECTION	Vikash bhaban -2	Metcas House	AWP090T0726363660SE	ACER P-IV 3.0 GHZ HDD-80 GB RAM - 256 MB	HPLJ 1020	UNILINE	Keyboard		
30	ROOM-44	DK	UPS				AARKAY APC	UPS		
31	P.S TO BFO	V.K	E-17	AWP140T1067015100SE				Computer Keyboard		
32	PS TO CEO	P.B	58	AWP140T1067015087SE	ACER P-IV 80GB HDD 1GB RAM	2055-DN SCX4521 FMFP	SUPRA	UPS		
33	PROJECT DIRECTOR	PB	37	1. ACER MACHINE 2. HP MACHINE				KEYBOARD, MOUSE, UPS Computer		
34	DIRECTOR(Admn.)	PB	7	ACER P-4				MONITOR		
35	INSTITUTIONAL ALLOTMENT (IA)	VK	C-5	P-III MACHINE		HP-3325 DJ		PRINTER		
36	ALLOTMENT BRACHH	VK	C-11	INTEL P-4				CPU, KEYBOARD, MOUSE		
37	AD(DEMOLITION)	VK	B-8	INTEL P-4		HP-6L-GOLD		CPU, KEYBOARD, MOUSE, PRINTER		
38	FO To CE(S)	(V.K)	E-7	AWP23GT2428466094ZE	ACER POWER SERIES	HP LJ 1007	SUPRA	Mouse Keyboard		
39	COMPUTER CELL	P.B.	15	AWPO90TO 736363703SE	ACER P-IV 3.0 GHZ HDD-80 GB RAM - 256 MB		MICROTEC K	Keyboard Mouse		

<b>INVENTORY FOR ONE TIME REPAIR OF COMPUTER &amp; ACCESSORIES IN DUSIB</b>										
S.NO	SECTION	ADD	ROOM NO.	CPU SERIAL NO.	PROCESSOR / MOTHER BOARD	PRINTER	UPS	Possible Faulty Parts & Unit	Repair/Replacement Cost Item-Wise (in Rs)	TOTAL
<b>RAJA GARDEN, ADJACENT TO DTC TERMINAL, NEAR SHIVAJI COLLEGE- (9717999146,9717999144)</b>										
1	DD-I, RAJA GARDEN							MOUSE		
2	ENQUIRY OFFICER	RAJA GARDEN			ACER P-4	LJ 6L		UPS, PRINTER, MOUSE		
3	A.C-A(C) -I		202/3	AWPO90TO7383819	P-4(ACER) (256MB)			CPU		
<b>MAHARANI BAGH, ON RING ROAD, 1 No. KILOKARI (DUSIB, NCT OF DELHI) - (9717999115, 9717999150)</b>										
1	DD- VI	---	1	2F-ADA81	INTEL P-III 866MHZ 120MB 20GB HDD		ELNOVA	UPS		
2	DD-VI			AWP090T072636369 5SE	ACER P-IV 80GB HDD 256 MB RAM	HP LJ-1020	UNILINE	UPS		
<b>MAHARANI BAGH, ON RING ROAD, 1 No. KILOKARI (DUSIB, NCT OF DELHI)</b>										
3	DD-III			AWP090T072636376 5SE	ACER P-IV 80GB HDD 256 MB RAM			Monitor UPS Keyboard		
4	DD-V		III- FLOOR			HP LJ-1020		Printer UPS		



INVENTORY FOR ONE TIME REPAIR OF COMPUTER & ACCESSORIES IN DUSIB										
S.NO	SECTION	ADD	ROOM NO.	CPU SERIAL NO.	PROCESSOR / MOTHER BOARD	PRINTER	UPS	Possible Faulty Parts & Unit	Repair/Replacement Cost Item-Wise (in Rs)	TOTAL
<b>COMMUNITY CENTRE SEELAM PUR, (DUSIB, NCT OF DELHI), OPPOSITE WELCOME METRO STATION, NEAR MANDIR</b>										
1		ASSTT. DIR.(EZB)			P-III, 20 GB HDD, 64 MB RAM	DJ-1560	ELNOVA	CPU, UPS, PRINTER		
<b>TEES HAZARI COURT COMPLEX, (DUSIB, NCT OF DELHI), ROOM No.-117, FIRST FLOOR, (9717999142)+A90</b>										
1	COMPETENT AUTHORITY		117	SGHJ450525/160GB	CPU.1.6/945/1GB, (HP 7540 SERIES0	HP LASERJET 1005	UNILINE	Printer -CPU - HDD -UPS		
<b>Other Printers Repair Cost (Excluding HP6L &amp; HP1000 Printers)</b>										
1	A.D.(SYSTEM) (H.Q.)	P.B.	43	AWP23GT13291564 01ZE	acer power series	HP LJ 6L HP 1020	APC	Printer (6L) Printer (1020)		
2	ROOM-44 (H.Q)	P.B.	PRINTE R			HP-2700 HP-LJ-1007		HP-2700		
<b>RANA PRATAP BAGH, NEAR SHKTI NAGAR CHOWK, BY THE SIDE OF DTC ( BOUNDARY 9717999112)</b>										
1	CD-III			AWP090T726363760 SE	ACER P-IV 80GB HDD	HP LJ-1020	ELNOVA UNILINE	ONE UPS		
2	DD-IV	(R.P. BAGH)		AWP090T072636373 SE	ACER P-IV 80GB HDD	HP LJ-1020	UNILINE	UPS		
3	ED-II	(R.P. BAGH)			ACER P-IV 80GB HDD			MONITOR		
4	ED-II	(R.P. BAGH)			ACER P-IV 80GB HDD			MONITOR		
5	ACA			AWP090T072636370 8SE	ACER P-IV 80GB HDD	CD-III HP LJ1020	UNILINE	UPS		

INVENTORY FOR ONE TIME REPAIR OF COMPUTER & ACCESSORIES IN DUSIB										
S.NO	SECTION	ADD	ROOM NO.	CPU SERIAL NO.	PROCESSOR / MOTHER BOARD	PRINTER	UPS	Possible Faulty Parts & Unit	Repair/Replacement Cost Item-Wise (in Rs)	TOTAL
<b>RAGHUBIR NAGAR, HORTICULTURE DEPTT., BEFORE GHODAWALA MANDIR (DUSIB, NCT OF DELHI)- (9717999136)</b>										
1	DY.DIR.(HORT.)				ACER P-4			CPU Hanging & UPS		
<b>MALKHA GANJ, (DUSIB), COMMUNITY CENTRE, FIRST FLOOR, (9717999132)</b>										
1	CPD MALKHA GANJ	---	1		ACER MACHINE P-4	LJ 1020	ELNOVA	UPS		
<b>INDIA HABITAT CENTRE, LODHI COLONY(DUSIB), III RD FLOOR, (9891901938)</b>										
1	MONITORING	MANMEE T	III-FLOOL	AWP070T2876123666SE	P-IV/256/80	HP-LJ-1000	ELNOVA	UPS		
2	MONITORING	JS. USHA MEHRA	III-FLOOL	2F-TG167	P-IV/128/20	HP LJ 1020	ELNOVA	UPS		
3	MONITORING	DR. BHORE LAL	III-FLOOL	AWP07ET011538328	P-IV/256/80	HP LJ 1020	UNILINE	UPS, CPU		
	<b>(A) UPS Batteries:</b>									
							<b>Nos.</b>			
	(i) In Comp. Cell :3.0 KV (12 V /17 AH)						16 Nos.			
	(ii) In Comp. Cell :1.5 KV (12 V / 26 AH)						3 Nos.			
	(iii) In HQ/DIV./Cir: (12V/7AH) 600/650 VA						52 Nos.			
	<b>(B) Portable Hard Disk (1- Tera Bite) Seegate/Weston make</b>									
	1 No.									
	□									