

Part I
Dispatch No. D/31/EE/11/C-7/2017 Date: 14/8/17

Sub: Testing of Bricks/Brick tiles for Water Absorption / Efflorescence.

A.L. No. WJ/631/09/CW/EEC-7/2017-18/D-618 Date: 24/8/17

1. Name of Work:-
SH:-

St. Imp. and Rehabilitation of Khas. Dwellers
Imp. of Common toilet and Common passage in part of lot No
184, 262, 654/18 (In No 8404)

2. Details from where sample is collected

do -
Circle 3/C-7

3. Name of Circle/Division

4. Name of Junior Engineer

5. Name of Assistant Engineer

Vijay Arora

6. Name of Executive Engineer

Sh. K.B. Sharma

7. Name of Contractor/Agency

Sh. Jamal Akhtar

8. Name of Officer Collecting Sample

Vijay Arora

9. Date of Collection/Date of filling frog.

11/8/17

10. Date of testing :

A.S.I.T

11. Identification Mark :

CD7-5

12. Class designation :

13. No. of Specimen Sent for testing :

5.5 x 2.10 cm

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample/samples marked..... has/have been taken in my presence which represent 10, some quantity of works/supply made at site/store.

Signature of JE
In Charge of work

Signature of Contractor

Signature of Officer
taking Sample (EE/AE)

Part II

TEST REPORT

No. SE(QC)/AE(Lab)/2016-17/D- 1504
Test No. 1107
Date of Receipt:- 16/8/2017

Date:- 09/09/17
Date:- 16/8/17

(A) WATER ABSORPTION:-

Date of testing up to:- 24/8/17

S. No.	Dry. Wt. (Gms)	Wet. Wt (Gms)	Water Absorbed (Gms)	% age Water absorbed	Average Water absorption
1.	3053	3459	406	13.298	
2.	2970	3390	420	14.14	
3.	3108	3580	472	15.19	14.83
4.	2998	3476	478	15.94	
5.	3053	3529	476	15.59	
6.					ACCEPTABLE

(B) EFFLORESCENCE:

Date of testing up to: 04/9/2017

Efflorescence found: Nil/Slight/Moderate/Heavy **ACCEPTABLE**

Only testing has been conducted in this laboratory. The sample/samples has/have been collected and handed over by the field staff of the concerned Division.

COPY TO:-
1 EE/C-7
2 ac

[Signature]
04/9/17

Assistant Engineer (QC Lab)