

The Assistant Engineer(QC)  
Quality Control Lab., DUSIB  
Vikas Kutir, ITO, New Delhi

R.No 2820  
RECEIVED 29 MAR 2017.

Part I  
Dispatch No D-1723/ESC/6/DUSIB/16-17 Date: 29/3/17  
Sub: Testing of CC cubes of mix M-15 for 28 days Compressive Strength.

A. L. No. 28/WJ-6981(97)/EE C-6/DUSIB/2016-17/D-600 dated .26.07.2016

Name of work: EIUS  
SH: P/L CC pavement in deteriorated lanes of JJ Basti at Janta Jeevan Camp, near Over Head Tank, Okhla Ind. Area Ph-II.

1. Details from where sample is collected	Site-----
2. Name of Circle/Division	Circle-II/C-6 -----
3. Name of Junior Engineer	Sh. Ramesh Kumar-----
4. Name of Assistant Engineer	Sh. Amarnath-----
5. Name of Executive Engineer	Sh. O.P Pruthi-----
6. Name of Contractor/Agency	M/S Vinod Prakash Enterprises-----
7. Name of Officer collecting sample	Sh. Amarnath/Sh.O.P. Pruthi-----
8. Date of collection:	<u>27-2-17</u>
9. Date of testing:	<u>29-3-17</u>
10. Required strength:	As per CPWD Specification, -----150 Kg/sqm---
11. No. of specimen sent for testing:	-----
12. Size of specimen:	15 X 15 X15 cm-----
13. Mark of specimen:	---A-----

Specimen relating to work mentioned above is/are sent for testing. It is certified that the sample samples marked---A-----has/have been taken in my presence which represent 30 m3 approx quantity of works/supply made at site/store.

Signature of JE in charge of work: [Signature]  
Signature of Contractor: [Signature]  
Signature of Officer taking sample (AE/IE): [Signature]

Part II  
No. SE(QC)/AE(Lab.)/2016-17 /D- 4878 Date: 29/3/17  
Test No. 2820 Date: 29.3.17  
Date of Receipt: 29.3.17  
Date of testing: 29.3.17  
Concrete Mix: M-15 Days test: 28/30 days

Sl. No	Wt. of specimen in gms	Area in sq.cm.	Compressive Strength		Average Strength (Kg./sq.cm)	Remarks
			Load (Tonnes)	Comp. strength (Kg./sq.cm)		
	7974	225	41.00	182.22	190.37	EE May Correlate Accordingly
	8012	225	42.50	188.89		
	8074	225	45.00	200.00		

Tested in my presence [Signature]  
Only testing has been conducted in this laboratory. The sample/samples has/have been collected and handed over by the field staff of the concerned division.

COPY TO:  
1. EE/C-6  
2. d/c

[Signature]  
29/3/17  
Assistant Engineer (QC)  
Delhi Urban Shelter Improvement Board