






INSPECTION OF NIGHT SHELTERS (AASHRAY ADHIKAR ABHIYAN) AT PHOOL MANDI BUILDING, MORI GATE, DELHI
Code No. 1105116




1.	Date of inspection	19/12/2014 & 26/12/2014
2.	Name and code No. of the Shelter	Phool Mandi Building, Mori Gate and code no. 1105116
3.	Name of NGO/Organization running the shelter	Prayas NGO (taken over from Ashriya NGO on 28.11.2014)
4.	Number of inmates Male/Female separately	Only male inmates. No female inmates. The utilization is as follows: 23/12-128 24/12-32+132 25/12-36+126
5.	Facility of Drinking Water	Yes
6.	Facility of Toilet	Yes, the same is being (furbished)
7.	Facility of Bathroom	Under refurbishment
8.	Arrangement for Cleanliness Status of Cleanliness	Sewer is overflowing.
9.	Details of Clothing/blanket provided to inmates during Night	Blankets provided
10.	Whether there is provision of Kitchen or not	Yes but was locked on 19.12.2014 (Photos of 26.12.2014 are enclosed)
11.	Type of Building/Tent Whether covered/open	Covered pucca structure Covered
12.	Arrangement for separation of Male/Female inmates	Under renovation.
13.	Lighting arrangement Sufficient/insufficient	Yes
14.	Security Guard	Yes
15.	Firefighting equipment	Yes
16.	Tank capacity for drinking/bath water	
17.	Photos of cleanliness	Enclosed. Sever is overflowing.
18.	Any other observation	1.Work needs to be speeded up as heavy winter has already commenced in Delhi. The temperature has dipped to 5 degree Centigrade, but the refurbishing work is slow (under utilized capacity) 2.Photographs of the Night Shelter taken of 19.12.2014 is enclosed. 3.Photographs of the Night Shelter taken of 26.12.2014 is enclosed 4.DUSIB needs to be work on maintenance immediately without delay of even a day.

(Prashant Kumar Panda)
Spl. Development Commissioner,
Delhi.

Photographs of 19.12.2014







Photographs dated 26.12.2014

