


## INSPECTION REPORT OF NIGHT SHELTER

1	Date of Inspection	26.12.2014				
2	Location/Name and Code Of Night Shelter	Jhandewalan Mandir (Near Petrol Pump) (Code-139)				
3	NGO/orgn. running the Shelter	Aashray Adhikar Abhiyan.				
4	Number of inmates	<table border="1"><thead><tr><th>Code</th><th>Inmates</th></tr></thead><tbody><tr><td>139</td><td>8</td></tr></tbody></table>	Code	Inmates	139	8
Code	Inmates					
139	8					
5	Facility of drinking water	Broken tap of drinking water tank.				
6	Facility of Toilet	Yes (Four) Toilets were in bad and unhygienic condition.				
7	Facility of Bathroom	No				
8	(a)Arrangement for cleanliness (b)Status of Cleanliness	Yes Poor sanitary conditions				
9	Details of clothing/blanket Provided to inmates during night	Blanket-51 number Rugs-25 number Mattress-23 number				
10	Whether there is provision of Kitchen facility	No				
11	Type of Building/Tent Whether covered/open	Portacabin/ Covered				
12	Arrangement for separation for Male/Female inmates	Only males in the shelter.				
13	Lighting Arrangement	Inside-Adequate Outside-Poor				
14	Any other observation	1) The lighting outside the shelter needs to be improved. 2) Bathrooms need to be provided, at present they use toilets as bathrooms.				
15	Attendant Name	Mr. Akash Mobile-7838673632				

  
26/12/2014